# BRUHAT BANGALURU MAHANAGARA PALIKE

## COMPLETION REPORT

| | | |
|---|---|---|
| 1 | Name of the work | Maintenance and repairs to D.G Set at Dasarahalli zone. |
| 2 | Sanctioned Estimate No. & Date | EE(Ele)/DZ/EST/ / Dated: 2.8.2012 |
| 3 | Head Of Account | P-0303 M & R to pumpsets/Wireless/Internal Telephone exchange |
| 4 | Origenal Work Order No & Date | EE(ELE)/DZ/WO/ 18/2012-13 Dt:07.11.2012 |
| 5 | Online Work Order No & Date | EE(ELE)/DZ/WO/ 000015/2017-18 Dt:03.02.2018 |
| 5 | Name Of the Contractor | M/s Power Mac |
| 6 | a) Time stipulated for Completion Work<br>b) Delay in Execution Of Work | 365 Days |
| 7 | Measurement Recorded in | M.B No: 5126/2017-18, Page No:512553 to 512555 |
| 8 | Check Measurement of the AEE/EE/on | M.B No: 5126/2017-18, Page No:512553 to 512555 |
| 9 | Name of the official incharge of the Work | |
| | a)Asst. Engineer/ Junior Engineer | Sri.K N Babu Reddy |
| | b) Asst. Executive Engineer | Sri , Rajendra Naik |

| Sanctioned Estimate Amount | Amount claim as Per Actually vide as Bills | Difference | |
|---|---|---|---|
| | | Excess | Saving |
| Rs.80000/- | Rs.83733/- | Rs.3733/- | Rs. |

1) Certified that the Contractor has delayed and completed the work for which necessary fine has been recovered.
2) Certified that the above work has been executed by the contractor satisfactorily in accordanee with the specifications as embodied in the Agreement.

K.N. Babu

Asst/Junior Engineer.

Asst.Exe.Engineer(Ele)
Bruhath Bangalore Mahanagara Palike
Dasarahalli Zone.

Executive .Engineer(Ele)
Bruhath Bangalore Mahanagara Palike
Dasarahalli Zone

Scanned by CamScanner